


Pins 1, 2, 20, 22, 23, 27, 28 from 27C64 are bended upside and are not in socket.
 Pins 1, 2, 20, 22, 23, 26, 27, 28 from 62256 are bended upside and are not in socket.



All given inputsignals only valid on 600 Rev.B !

Datum: 28.11.10

Maßstab: 100,00%

Projekt:

Name:

letzte Änderung: 28.11.10

OSI 600 Rev.B RAM-Upgrade